


Application Fact Sheet - Screw Conveyor Cost Savings



Animal Feed Screw Conveyor

Screw Conveyor Shaft Wear Solution



The Application Problem


A customer was having problems with rubbing seals which were creating excessive wear and damage to screw conveyor shafts on an animal feed conveyor. This created high maintenance costs and limited operational use of the conveyor.

To cope with these problems, the customer had a regular bearing change-out and shaft rebuild during the annual maintenance period which incurred regular shaft rebuild costs in the region of £350. An additional bearing changeout was also required during production every year.



Above: Typical annual shaft damage prior to conversion.

Below: Wear collars shown in position before fitting of housing.



The Cooper Split Solution

To rectify the problem, Cooper recommended shaft wear collars to be fitted to either side of the 01E 90mm EX (Expansion) bearing installed in a special strap hanger application on the shaft of the screw conveyor.

The application required special modification to the cartridge and enabled the screw conveyor to operate continuously throughout the processing period without the need for any bearing or seal related stoppage. This has resulted in significant cost savings for the customer.


Prior to conversion the estimated maintenance costs for a full equipment change is estimated at:

Complete shaft and screw unit: _____	£8,000	(\$12,000)
Maintenance Cost: Minimum of 2 days: _____	£1,000	(\$1,500)
Crane Hire: _____	£1,000	(\$1,500)
Potential Cost Savings: _____	£10,000	(\$15,000)

The Cooper hallmark split to the the shaft feature permits inspection and maintenance to be carried out in the shortest possible time making a positive contribution to profitability.

The Cooper wear collar solution has enabled a continuous production period without a bearing change for the first time in fifteen years.

Below: Installation of cartridge in screw conveyor.



All information and figures correct at time of printing.

Photographs with permission of the customer.

Customer Service Centres

UK, Africa, Asia, Australasia and the Middle East

Cooper Roller Bearings Co Ltd
Wisbech Road
King's Lynn
Norfolk PE30 5JX
England.
Telephone +44 (0) 1553 763 447
Fax +44 (0) 1553 761 113

Europe and South America

Cooper Geteilte Rollenlager GmbH
Postfach 100 423
Oberbenrader Str 407
47704 Krefeld
Germany.
Telephone + (49) 2151 713 016
Fax +(49) 2151 713 010

USA and Mexico

The Cooper Split Roller Bearing Corp.
5365 Robin Hood Road, Suite B
Norfolk, VA 23513
USA
Telephone 757 460 0925
Fax 757 464 3067

Canada

Cooper-Grainger Canada Inc
5875 Coopers Avenue
Mississauga
Ontario L4Z 1R9
Canada
Telephone 905 890 2266
Fax 905 890 2269